Printed on: 1/18/2009 7:17:29 AM

National Transportation Safety Board		NTSB ID: ERA09WA084				Most Critical Injury:				
PRELIMINARY REPORT			Occurrence Date: 12/03/2008				Investigated By: Foreign			
AVIATION ETYBON			Occur	Occurrence Type: Accident						
Location/Time										
Nearest City/Place State		State		Zip Code	Local Time		Time Zone	ime Zone		
Cordoba, Colombia					1835		EST			
Aircraft Information										
Registration Number	ration Number Aircraft Manufacturer							Model/Series Number		
HK1697	AERO CON	MMANI	ANDER 500							
Type of Aircraft:			Amateur Built Aircraft?							
Injury Summary:	Summary: Fatal 2			Serious Minor		Minor			None	
Revenue Sightseeing Flight: Air				Air Medical Transport Flight:						

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On December 03, 2008 about 1835 eastern standard time, an Aero Commander 500, of Colombian registration, HK1697, registered to an individual and operated by Taxi Aero Caribeno LTDA, crashed in an open field, near Cordoba, Colombia. Visual meteorological conditions prevailed and a visual flight plan was filed. The pilot and the copilot were killed, and the airplane was destroyed. The flight originated from the Olaya Herrera International Airport (SKMD), Medellin, Colombia, earlier that day, at an unspecified time. The flight destination was to Los Garzones Airport (SKMR), Monteria, Colombia.

According to information obtained from the Colombian Civil Aeronautical Authorities, the air traffic controller at Barranquilla authorized the flight, once at the intersection of IRETO, at an estimate time of 1830 to 1840, to descend to 5,000 feet and to report at 15 miles from the MTR VOR. The crew never communicated with the Barranquilla controllers for the position report. A search and rescue operation was launched. A military aircraft spotted an unusual heat source in an open field. The local police investigated the source and discovered the missing airplane.

This investigation is under the jurisdiction of the Government of Colombia. Any further information can be obtained from:

Unidad Administrativa Especial de Aeronautica Civil

Aeropuerto Internacional El Dorado

Bogota, Colombia

Telephone: 571.425.1000

This report is for informational purposes only, and contains information released by the Government of Colombia.

TRANSO_
National Transportation Safety Board
0 7
PRELIMINARY REPORT
2 3 €
AYIATIQN

NTSB ID: ERA09WA084

PRELIMINARY REPORT AVIATION		Occurrence Date: 12/03/2008										
		Occurrence Type: Accident]					
Other A	ircraft Involved		•									
Registration Number Aircraft Manufacturer							Model/Series Number					
Accider	nt Information											
					dent C	Occurred Durin	ng:					
				•								
Crew	N	ame				Certificate No.						
Pilot	On File											
2												
3												
4												
5												
6												
Operator Information												
Name Operator Designator Code Doing Business As Taxi Aero Caribeno LTDA												
Street Address City Med						n, Colombia		State Zip Code				
-Type of	Certificate(s) Held: Nor	ne		•								
Air Carri	er Operating Certificate(s):										
Operating Certificate:					0	perator Certif	icate:					
Regulation	on Flight Conducted Unc	ler: Non-U.S., Non	-Commer	rcial	•							
Type of F	light Operations Conduc	ted: Personal										
Flight F	Plan/Itinerary											
Type of	Flight Plan Filed: VFR								_			
Last Departure Point						State	Airport Identifier					
Medellin							SKMI	D				
Destination						State	Airport	Identifier				
Monteria							SKMI	R				
Weathe	er Information											
Investigator's Source:						facility ID: SKRG Observation Time (Local): 1800)		
Sky/Lowest Cloud Condition: Scattered					1800 Ft. A	AGL						
Lowest Ceiling: Ft. AGL Visibility: 10 SM Altimeter: 30.2					30.21	"Hg						
		PRELIMINARY	INFORM	ATION -	- SUI	ВЈЕСТ ТО С	CHANC	GE	•			Page 2

National Transportation Safety Board PRELIMINARY REPORT

NTSB ID: ERA09WA084

PRELIVENARY REPORT			Occurrence Date: 12/03/2008						
AVIATION			rrence T	ype: Accident					
Weather Information)								
Temperature: 19 °C	Dew Point:	14 °C	Wind D	irection: 70					
Wind Speed: 3 Kts	Gusts:	Kts.	Weathe	er Conditions at Accident S	Site: Visual Conditions				
Administration Data									
Notification From					Date				
Colombian Civil Aviation Aut	ho								
FAA District Office/Coordinator		Investigator-In-Charge (IIC)							
FAA/IFO Javier Rodriguez				Jose Obregon					